



# NEWPARK ENVIRONMENTAL SERVICES

## GAS DETECTOR CALIBRATION

### BW GasAlertMax XT

Date Calibrated: 11-26-08

Unit Serial #: MA108—007479 (NID)

Calibrated By: (b) (6), (b) (7)(C)  
(Print)

Calibrated By: (b) (6), (b) (7)(C)  
(\*Signature)

Next Calibration Date: 12-26-08

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*date meter received*



# NEWPARK ENVIRONMENTAL SERVICES

## GAS DETECTOR CALIBRATION

### BW GasAlertMax XT

Date Calibrated: 12 - 3 - 08

Unit Serial #: MA108—007479 (NID)

Calibrated By: (b) (6), (b) (7)(C)  
(Print)

Calibrated By: (b) (6), (b) (7)(C)  
(Signature)

Next Calibration Date: 01 - 05 - 08

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*No longer in service*



## NEWPARK ENVIRONMENTAL SERVICES

### GAS DETECTOR CALIBRATION

BW GasAlertMax XT

Date Calibrated: 1/8/09

Unit Serial #: MA108-<sup>0091663</sup>~~007479~~ (NID)

Calibrated By: (b) (6), (b) (7)(C)  
(Print)

Calibrated By: (b) (6), (b) (7)(C)  
(Signature)

Next Calibration Date: 1/7/09

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



## NEWPARK ENVIRONMENTAL SERVICES

### GAS DETECTOR CALIBRATION

#### BW GasAlertMax XT

Date Calibrated: 2/2/09


Unit Serial #: MA108 <sup>009663</sup> ~~007479~~ (NID)

Calibrated By: (b) (6), (b) (7)(C)  
(Print)

Calibrated By: (b) (6), (b) (7)(C)  
(Signature)

Next Calibration Date: 3/1/09

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# NEWPARK ENVIRONMENTAL SERVICES

## GAS DETECTOR CALIBRATION

### BW Gas Alert Max XT

Date Calibrated: 3/2/09


Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (print)  
(Signature)

Next Calibration Date: 4/1/09

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# NEWPARK ENVIRONMENTAL SERVICES

## GAS DETECTOR CALIBRATION

### BW Gas Alert Max XT

Date Calibrated: 3/2/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)


(Signature)

Next Calibration Date: 4/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 4/2/09

Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)


(Signature)

Next Calibration Date: 5/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 4/2/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)

Calibrated By: (b) (6), (b) (7)(C) (Signature)


Next Calibration Date: 5/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 5/1/09

Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)


(Signature)

Next Calibration Date: 6/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 5/1/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C)


(Signature)

Next Calibration Date: 6/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 6/1/09

Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C)


(Print)

(Signature)

Next Calibration Date: 7/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 6/1/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)


(Signature)

Next Calibration Date: 7/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 7/1/09

Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)


(Signature)

Next Calibration Date: 8/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 7/1/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)


Calibrated By: (b) (6), (b) (7)(C) (Print)

(Signature)

Next Calibration Date: 8/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 8/3/09

Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (print)

(Signature)


Next Calibration Date: 9/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 8/3/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)

(Signature)


Next Calibration Date: 9/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 9/1/09


Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)

Next Calibration Date: 10/1/09  
(Signature)

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 9/1/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)


Calibrated By: (b) (6), (b) (7)(C) (Print)

Next Calibration Date: 10/1/09 (Signature)

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 9/30/09

Unit 2 Serial #: MA108-009663 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)


(Signature)

Next Calibration Date: 11/1/09

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



NEWPARK ENVIRONMENTAL SERVICES

GAS DETECTOR CALIBRATION

BW Gas Alert Max XT

Date Calibrated: 9/30/09

Unit 1 Serial #: MA109-002441 (NID)

Calibrated By: (b) (6), (b) (7)(C)

Calibrated By: (b) (6), (b) (7)(C) (Print)

(Signature)  
Next Calibration Date: 11/1/09

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_